

# BUS DRIVER'S VEHICLE INSPECTION REPORT

COWTOWN BUS CHARTERS INC.

COMPANY 5504 FOREST HILL DRIVE - FT. WORTH, TEXAS 76119 BUS NO. 106

## ODOMETER READING

END MILEAGE: 12723

DATE: 3-27-08

START MILEAGE: 10834

TIME: 9:50

AM  
 PM

TOTAL MILEAGE: 1889

LOCATION: SHOP

## INSPECT ITEMS LISTED - IF DEFECTIVE, NUMBER AND DESCRIBE IN "REMARKS"

- FLUID LEAKS UNDER BUS
- LOOSE WIRES, HOSE CONNECTIONS OR
- BELTS IN ENGINE COMPARTMENT
- OIL LEVEL
- RADIATOR COOLANT LEVEL
- BATTERY
- TRANSMISSION
- UNUSUAL ENGINE NOISE
- GAUGES & WARNING LIGHTS
- SWITCHES
- HORN
- FANS & DEFROSTERS
- WIPERS & WASHERS
- STOP ARM CONTROL (WARNING CONTROL)
- INSIDE & OUTSIDE MIRRORS
- BRAKE PEDAL & WARNING LIGHT
- OPERATION OF SERVICE DOOR
- EMERGENCY EQUIPMENT
- FIRST AID KIT
- ENTRANCE STEPS
- CLEANLINESS OF INTERIOR
- CONDITION OF FLOOR

- EMERGENCY DOOR & BUZZER
- HEADLIGHTS, FLASHERS & 4-WAY FLASHERS
- RIGHT FRONT TIRE & WHEEL
- FRONT OF BUS - WINDSHIELD
- LEFT FRONT TIRE & WHEEL
- STOP ARM (SCHOOL BUS)
- EXHAUST SYSTEM
- LEFT SIDE OF BUS - WINDOWS & LIGHTS
- LEFT REAR TIRES & WHEELS
- REAR OF BUS - WINDOWS & LIGHTS
- TAIL PIPE
- RIGHT REAR TIRES & WHEELS
- RIGHT SIDE OF BUS - WINDOWS & LIGHTS
- DRIVER'S SEAT AND BELT
- DIRECTIONAL LIGHTS
- PARKING BRAKE OR SERVICE BRAKE
- CLUTCH
- STEERING
- WHEELCHAIR LIFT

REMARKS pre OK

FUEL 99.137  
75.898

FAN BELT RUBBING ON OIL FILTER

CONDITION OF ABOVE VEHICLE IS:

SATISFACTORY

UNSATISFACTORY

DRIVER'S SIGNATURE: Rubio Perry

ABOVE DEFECTS CORRECTED

ABOVE DEFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE

MECHANIC'S SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_

DRIVER REVIEWING REPAIRS: SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_